Service Contract No. WD/04/2020

Development of Lok Ma Chau Loop: Main Works Package 1 – Environmental Team

Water Quality Monitoring Results on 4 June 2022

Weather Condition: Rainy

Location	Sampling	Depth (m)	Temperature (°C)		рН		Salinity ppt		DO Saturation (%)		Dissolved Oxygen (mg/L)		Turbidity(NTU)		Suspended Solids (mg/L)	
	Time		Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
CS1	09:11	0.5	30.0 29.9	30.0	7.4 7.4	7.4	0.1 0.1	0.1	74.5 75.1	74.8	5.6 5.7	5.7	18.1 18.2	18.2	18 17	17.5