## Service Contract No. WD/04/2020

## Development of Lok Ma Chau Loop: Main Works Package 1 – Environmental Team

Water Quality Monitoring Results on 8 June 2022

**Weather Condition: Rainy** 

Location	Sampling	Depth (m)	Temperature (°C)		рН		Salinity ppt		DO Saturation (%)		Dissolved Oxygen (mg/L)		Turbidity(NTU)		Suspended Solids (mg/L)	
	Time		Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
CS5	10:42	0.1	27.1 27.1	27.1	7.9 7.9	7.9	0.1 0.1	0.1	86.2 86.0	86.1	6.9 6.8	6.9	11.7 11.8	11.8	22 18	20.0